

Survey for Bob Lewis and others
in Sec. 6 T. 4 N. R. 29 E. M. M.

Feb. 1, 1910

Chains Links

From the N. W. cor. of sec. 6 T. 4 N. R. 29 E. M. M.
I ran east on true line

27 24 set ten $\frac{1}{16}$ sec. cor.
47 24 " " $\frac{1}{4}$ " "
67 24 " " $\frac{1}{16}$ " "
77 24 " " $\frac{1}{64}$ " "
87 24 " " Sec. cor.
246 81 to the closing corner to sec. 3 & 4
Wests on true line

127 72
198 32 7/8 set pipe for Sec. cor.

From the N. W. cor. of sec. 6 I ran south on
true line

43 45 set ten $\frac{1}{4}$ sec. cor.
53 45 " " $\frac{1}{64}$ " "
63 45 " " $\frac{1}{16}$ " "
83 87 to sec. corner.

North on true line

20 10 set pipe for $\frac{1}{16}$ sec. cor.
30 15 " " " $\frac{1}{64}$ " "
40 20 " " " $\frac{1}{16}$ " "

From the N. E. corner of sec. 6 I ran south
on random line

22 58 I set ten $\frac{1}{16}$ sec. cor.
42 58 " " " $\frac{1}{4}$ " " "

Chains Links

82 36 to S. E. cor. of Sec. 6.
North on true line

40 18½ set pipe for ¼ sec. cor.

60 27¼ " " " ¼ " "

From the S. W. cor. of Sec. 6 I ran east on true line

48 10 set tin stake

88 16 to sec. cor.

West on true line

40 03 set pipe for ¼ sec. cor.

From the ¼ sec. cor. on the west of sec. 6 I ran east on random line

17 67 set tin stake

27 67 " " "

37 67 " " "

47 67 " " "

57 67 " " "

67 67 " " "

77 67 " " "

88 05½ to ¼ sec. cor.

From the ¼ sec. cor. on the north of Sec. 6 I ran south on random line

22 38 set tin stake

43 18 to correct east and west line

63 18 set tin stake

83 38 ½ ¼ sec. cor.

North on true line

20 10 set tin stake

40 20 to correct ¼ sec. cor.

60 30 set pipe for ¼ sec. cor.

From the ¼ sec. cor. on the east of Sec. 6 I ran west on true line

10 04¼ set iron pipe for ¼ sec. cor.

Chain Links

20 08½ set iron pipe for ¼⁶ sec. cor.30 12¾ " " " " ¼⁴ " "40 17 to corrected ¼⁴ sec. cor.50 21½ set iron pipe for ¼⁹ sec. cor.60 25½ " " " " ¼⁶ " "70 29½ " " " " ¼⁴ " "

From the ¼⁶ sec. cor. on the west of the S.W. ¼⁴ of sec. 6 I ran east on true line

17 88 I set ten. stake

29 88 " " " "

48 00 to ¼⁶ sec. cor. stake

West on true line

20 05 set pipe for ¼⁶ sec. cor.30 07½ " " " " ¼⁴ " "

From the ¼⁶ sec. cor. in the center of the west ¼⁴ of the S.W. ¼⁴ of sec. 6 I ran north on true line

10 00 set ten. stake

20 09 to ¼⁶ sec. cor.

S. on true line

10 04½ set iron pin for ¼⁴ sec. cor.

From the ¼⁶ sec. cor. on the west of the N.W. ¼⁴ of sec. 6 I ran east on random line

29 45 I set ten. stake

37 45 " " " "

47 18 to ¼⁶ sec. cor.

West on true line

10 05¾ set pipe for ¼⁶ sec. cor.20 11½ " " " " ¼⁶ " "

From the ¼⁶ sec. cor. in the center of the north ¼⁴ of sec. 6 I ran east on true line

10 00 set ten. stake

20 00 " " " "

Chains Links

30 00 set turn stake
 40 22 to N^e sec. cor.

West on true line

10 05 $\frac{1}{2}$ set iron pipe for N^e4 sec. cor.
 20 11 " " " " N^e6 " "
 30 16 $\frac{1}{2}$ " " " " N^e4 " "

J. W. Kimball Co. Surveyors
 By George Kimball Deputy

Assisted by Robert Lewis Chamman

Wm. Whitwell "

John T. Walker flagman