

W Roberts Sister Kilo Palmer

June 23 1904 JIN 1896

Apex, Miles, Chains, Links

from the $\frac{1}{4}$ sec cor bet Secs 17 and 18 I run ~~west~~ east on random line through Sec 17
 50 50 the $\frac{1}{4}$ sec cor bet Secs 16 & 17
 38 85 the cor of Secs 5-8-16 & 17 these west on same line
 19 42 the bet post marked $\frac{1}{4}$ from which a pine 5 in bet 44 & 40 the bet
 built through center Sec 17
 the $\frac{1}{4}$ sec cor bet Secs 17 & 20

(continued from page 544)

and E. from the corner. The old stake was standing when we put up the fence and we run the fence to the corner and stake both from the E. and from the N. The first fence was built in 1874 or 1875. A number of fences have been built since then and I don't know whether they were put where the old fence was or not, but never heard of the location of the fence line running E. & W. being changed at the point where the corner stood.

Car. Sams thought the corner had been moved South but did not know anything about it having been moved and had never heard anything to that effect. His opinion was based, as he stated, on the fact that the corner was not in line with the corners E. and W. from the corner in question. I refer to the field notes of T. J. N. R. 35 E. and find that the length of the vision line on the E. of Sec 1 is given as 67.25' also between Secs 1 and 2 63.10' ^{also} between Secs 2 and 3 64.35' ^{also} making the corner in question over 2 $\frac{1}{2}$ chs. out of line
 (continued on page 546)