

Loring Wacker

June 17 1913

Sec 13 T 3 South Range 30 1/2 S

Chain Links

- Mark per Sec 13 218
- 40 22 Set Corn to Sec 12-13-7 5/8
- West per Sec 12 5 1/8
- 40 01 set paper to Sec 12
- 60 11 " " 1/8 "
- 82 50 Set Corn to Sec 11-12-13 9 1/4
- These best on True line
- 20 62 set Stone in mid of Stone to 12
- 41 25 set Stone 18 + 8 1/6 feet to Sec 12
- these points through center Sec 13
- 40 01 set paper to Sec 13
- 80 50 approx 100 No Corn off 1/4 Sec
- Mark on True line
- 40 51 True True Center Sec 13
- West through center Sec 13
- 20 00 set paper to 12
- 40 07 True center Sec 13
- 60 11 set paper to 12
- 80 50 True 1/4 Sec 12
- Best on True line
- 20 25 set Stone in mid of Stone
- 40 52 set Stone in mid of Stone to Corn
- 60 50 set Stone to 12 in center 1/2 Sec 13
- best from 1/4 Sec in Sec 13 T 3 S R 30 1/2 S
- 40 35 True line to 13-24-14 5/8

Sewer Marshal County Surveyor by Station at 10' interval every