

Survey of S. W. Bradley

Nov. 20 1913

S 5 N 16 29 E W m

Chain Links

East on South Boundary

40 01 Set Iron pipe $\frac{1}{4}$ Sec cor60 01 " " $\frac{1}{16}$ cor

80 74 a post - 24 lbs south of corner to Sec 33 334 This N 69° 57' W on true line

20 16 $\frac{1}{2}$ Set Iron pipe for $\frac{1}{16}$ cor40 37 Set Iron pipe for $\frac{1}{4}$ Sec corThese North through center S $\frac{1}{2}$ Sec 32

35 92 to center Sec 32 these Iron

South on true line

15 96 Set Iron pipe for $\frac{1}{16}$ corIron pipe at center S $\frac{1}{2}$ Sec 32 IronSouth through center S $\frac{1}{4}$ Sec 32

5 98 Iron pipe

15 96 Iron pipe

25 96 Set Iron pipe $\frac{32}{32}$ cor

35 92 to to cor these north

5 96 Set Iron pipe for fractional cor

John W. H. in here Deputy County Surge