



**NARRATIVE:**

This survey was for the purpose of pinning all deed corners of the shown lots. The basis of bearing was the West Section line as established by McLind in County Surveys #'s 85-21-A and 83-02-A. I found no survey of record for the creation of the 3.16 acre lot which is now a church parcel. I used the deeded distances to establish the lot corners. I found an unmarked 5/8" Iron Rod in the southeast corner of the Church lot that was located in the proper location and placed my cap on it. The pin in the Northeast corner of the church lot set by McLind appears to have been disturbed during the construction of the chain link fence. I did not replace or move this pin but noted its proper location. Other pins found disturbed were merely bent over but the McLind pins must have been moved to be off in distance that far. During my initial monument search I found the Section Corner in the southwest corner had been removed and was lying on the ground not far from its proper location. The County Surveyor reset the same monument and it appears to match the McLind surveys quite well.

**LEGEND**

- SET MONUMENTS - 5/8" X 30" Iron Rods W/ Plastic Caps Stamped - L.S. #2431
- Found Monuments as Noted
- Found Section Monuments as Noted
- Found P.K. in C.L. Pavement (as found in McLind Survey)
- Calculated Points Only (Not Set)
- SECTION LINE
- 000 Record or Deed Distances

Survey for  
 Vern & Penny Rodighiero  
 Township 6 North, Range 35 East, W.M.  
 Section 36, SW 1/4  
 January, 1994



SCALE 1" = 100 Ft.

ENGINEERING - SURVEYING - WATER RIGHTS  
**R V MCKINNIS ENGINEERING**  
 Rt 1 Box 1122 Hermiston, Oregon 97838  
 503-567-2017