

V-23

OREGON CORNER RESTORATION FORM

Section 36 Township 1 S Range 35 E

County UNION - UMATILLA Date 12-13-89



Corner Designation

1/4 CORNER COMMON TO SECTIONS 36 & 25	S26	S25	S30	<input checked="" type="checkbox"/> Condition Report Only <input type="checkbox"/> Not Found <input type="checkbox"/> Renewed <input type="checkbox"/> Unrecorded <input type="checkbox"/> Surveyed In <input type="checkbox"/> Referenced Out
		X		
	S35	S36	S31	
			S6	
	S1			

Previous Renewals/Surveys, etc.
Jacob Cooper, Contract # 397, 1881; Arnold G. Gibson, 1969,
OREGON STATE PARKS, 1989

Monument(s) & Accessories Found: (Condition and Source)
 Found 3" Bronze Cap on 1 1/2" (inside diam.) Galvanized Pipe,
 firmly set 9" above ground in mound rock.
 1882 6" Fir (Bearing Tree) bears N 10° E 12 links- no evidence
 found.
 1882 14" Fir (Bearing Tree) bears S 21° W 13 links; Now 26" White
 Fir, partially healed blaze, scribes 1/4 S BT visible.
 1969 10" Tamarack (Bearing Tree) (Now 12") bears N 24° E 50.8 feet
 to face // 51.3 feet to center of tree, single healed blaze,
 with yellow STATE FOREST TAG attached.
 1969 24" Douglas Fir (Bearing Tree) (Now 26") bears S 10° W
 19.2 feet to face // 20.3 feet to center of tree, single healed
 blaze.
 4" X 4" White Fir Post 1.5 feet N.45°W. of CAP & PIPE.

Monument Detail



Monument Set (Procedures and Description)
NONE

New Accessories
NONE

Location & Comments
Measurements taken
by hand compass and
steel tape.

Compass Declination
by: 20° E.
Oregon State Parks
& Recreation Department
525 Trade Street, S.E.
Salem, OR 97310

Surveyor's Seal



298



RECEIVED BY
 Umatilla County Surveyor
 Date 12-91
 Rec'd By KK
 No. 91-103-B

Party Chief: BILL HERMANN
 Notes: BILL HERMANN
 Witness: H. HANSON; S. DEJANAKUL