

OREGON CORNER RESTORATION FORM

Section 41 Township 31N Range 27E
County Umatilla Date 06-29-02

Corner Designation: 9N27E17

Condition Report Only
 Not Found
 Remonumented
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals / Surveys, etc.
Brass capped monument set by GLO in 1940.
Survey 90-49-B records finding this corner.

Monument and Accessories Found: (condition and source)

Found the GLO monument in good condition as shown below.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET

None.

Made GPS tie to TMT Station
Stanfield East Base
Latitude 45° 45' 26.3168" N
Longitude 119° 24' 50.6266" W
NAD 83 (1991)

Oregon State Plane Coord. - North Zone
Northing 763461.82
Easting 8479274.06
Ortho Height 630.11
Ellipsoidal Height 560.24

Location and Comments: Compass Declination 20° E

From junction of 184 and Westland Road, follow Jordan Road south 1.1 mile. Then follow the Madison Farm Road south another 0.7 mile. Then follow circle road southwesterly 2.5 miles. Then follow a circle road northwesterly 0.5 miles to the corner.

Surveyors Seal

RECEIVED BY:

Firm / Agency

Date: 12-01-02
Rec'd By: [Signature]
No: 02-282-9

Haddock Surveying
P.O. Box 1874
Pendleton, OR 97801
(541) 278-2174

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

RENEWS 6-30-03