

**OREGON CORNER RESTORATION FORM**

COUNTY: Umatilla DATE: June 25, 1998

CORNER DESIGNATION: R-15, North Quarter Corner of Section 27, Township 5 South, Range 31 East, W.M.

**PREVIOUS RENEWALS/SURVEYS ETC.:**

Original GLO Survey by George S. Pershin, under Contract No. 373, dated September 14, 1880. Record states: Set a basalt stone 18" x 12" x 5" in sag.  
A pine 16" diameter bears N 48° W, 134 lks. No tree on South side.

**MONUMENT AND ACCESSORIES FOUND:**

The original Northwest bearing tree with scribe marks visible bears N 48° W, 88.4 feet to face of blaze and 88.9 feet to centerline of tree.

**MONUMENT MARKING DETAIL:**

T5S R31E  
1/4 S22  
S27  
1998  
PLS 1106

**MONUMENT SET:**

At a point S 48° E, 88.4 feet from face of blaze, set a 2 3/8" brass cap on a 1 1/4" x 30" galvanized iron pipe 3" below surface of Ukiah-Granite Highway, in Southbound lane, (Road construction has removed original corner stone).

**New Accessories:**

A 5/8" x 30" iron rod with yellow plastic cap stamped "OR PLS 1106, WA PLS 17372", bears N 29° E, 59.1 feet.

A 5/8" x 30" iron rod with yellow plastic cap stamped "OR PLS 1106, WA PLS 17372", bears S 41° E, 86.6 feet.

A 12" diameter ponderosa pine scribed "1/4S27BT" bears S 18° W, 126.8 feet.

A 9" diameter ponderosa pine scribed "1/4S22BT" bears N 51° W, 86.9 feet.

All accessories have bearing object signs attached.

5/8" iron rods have steel fence posts 1.0 feet beyond with witness post attached.

**LOCATION AND COMMENTS:**

COMPASS DECLINATION: 18° East

Surveyor's Seal

Witnesses: Jason Wells  
John Linder, LSIT



Renews 6-30-2000

RECEIVED BY  
Umatilla County Surveyor  
Date 7-98  
Rec'd By AK  
No. 98-1462