

and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 848499.39

E = 8795856.10

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM: HDJ Design Group
5 N. Colville, Suite 200
Walla Walla WA 99362

WITNESSES: Thomas J. Boshart
Felipe G. Hernandez

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Greg E. Flowers
OREGON
JUNE 30, 1997
GREG E. FLOWERS
02820LS

RENEWS 12/31/15

06/29/2015

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 06/23/2014

CORNER DESIGNATION: T-17, Quarter Corner Section for Sections 27 and 26, Township 6 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set post for quarter section corner for Sections 27 & 26, from which a Tamarack 10 inch diameter bears S70°E, 24 links distance, a Red fir 4 inch diameter bears N10°W, 15 links distance.

Surveyor Paul W.P. Tomkins noted in his February 15, 1996 survey, shown on Umatilla County Survey record of surveys 99-121-B, "West ¼ Corner of Section 26, and East ¼ Corner of Section 27. History: Corner was originally established in 1872 by George Williams, U.S. Deputy Surveyor, under Contract No. 176, as a post, from which a Tamarack 10" in diam., bears S 70°E., 24 lks (15.84') dist., and A Red fir, 4" in diam., bears N 10°W., 15 lks (9.9') dist. Evidence Found: A East-West fence 15' North of Corner, A down 18" Tamarack Log, blaze evident, no scribe, N 70°W., 15.8' distance from corner, and a 12" Red fir stump, bears N 10° W, 9.9' distance from corner. Corner Perpetuation: Set a 5/8" x 30" rebar with yellow cap stamped "Tomkins Surveying," with the following bearing trees for accessories: A Tamarack, 8" in diam., bears S 29°08'00" W., 8.20' dist., and a White Fir 16" in diam., bears N 14°36'00" E, 21.4 dist.

Surveyor Paul W.P. Tomkins noted in his October 15, 1999 survey, shown on Umatilla County Survey record of surveys 99-258-C, found a 5/8" x 30" rebar with yellow cap stamped "Tomkins Surveying," with the following bearing trees for accessories: A Tamarack, 8" in diam., bears S 29°08'00" W., 8.20' dist., and a White Fir 16" in diam., bears N 14°36'00" E, 21.4 dist.

MOUNUMENT AND ACCESSORIES FOUND:

Found 5/8" iron rebar with yellow cap marked "Tomkins Surveying" from which was also found:
A Tamarack, 10" in diam., bears S 29°W., 8.20' dist., with healed blaze and bearing tag.
A White fir, 20" in diam., bears N 9°E., 21.40' dist., with healed blaze.
Remnants of a Fir stump, bears N 10°W., 9.90' dist.,
An E-W barbed wire fence approximately 65.00' north of corner.

MOUNUMENT MARKING DETAIL:

T6N R37E
S27 | S26
¼
2014
LS 02820

MOUNUMENT AND ACCESSORIES SET:

At the position of the found iron rebar, set a 1½" x 30" galvanized iron pipe with a 2½" brass cap +/- .5 above ground, stamped as the quarter corner common to Sections 27 and 26, Township 6 North, Range 37 East from which was set:

A White fir, 10" in diam., bears S 89°W., 25.60' dist., marked "T6N R37E ¼ S27 BT"
A Douglas fir, 16" in diam., bears N 71 E., 26.00' dist., marked "T6N R37E ¼ S26 BT"

LOCATION AND COMMENTS:

Corner is on a very gentle north slope amongst timber. Bearings taken with Silva hand compass