

**OREGON CORNER RESTORATION FORM**

**COUNTY:** Umatilla    **DATE:** 01/06/2015

**CORNER DESIGNATION:** X-9, Quarter Corner for Sections 32 and 33, Township 6 North, Range 37E, W.M.

**PREVIOUS RENEWALS/SURVEYS ETC:**

Originally surveyed by A.H. Simmons for Deputy Surveyor George Williams under his contract No. 176 dated October 23, 1872; his notes state "Set post in mound of stone for corner quarter sections 32 & 33.

**MOUNUMENT AND ACCESSORIES FOUND:**

No evidence found.

**MOUNUMENT MARKING DETAIL:**

LS 02820  
T6N R37E  
S32|S33  
1/4  
01/2015

**MOUNUMENT AND ACCESSORIES SET:**

At the surveyed position, set a 2½" brass cap on 1½" galvanized iron pipe, marked quarter corner for sections 32 and 33, T6N, R37E by LS 02820 01/2015. Set 6 inches above ground, from which:  
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N65°W, 9.00 feet.  
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N60°E, 12.00 feet.  
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S75°W, 6.00 feet.  
Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S44°E, 13.00 feet.

**LOCATION AND COMMENTS:**

Set in high brush on a northeast facing slope. Bearings taken with Silva hand compass and distances measured with a steel tape.

**OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:**

N = 842823.95  
E = 8785688.26

**COMPASS DECLINATION:** 15° East


**SURVEYORS' SEAL:**

**FIRM:** HDJ Design Group  
5 N. Colville, Suite 200  
Walla Walla WA 99362

**WITNESSES:** Joseph R. Latimer  
Corey A. West



*Greg E. Flowers*



RENEWS 12/31/15

*06/29/2015*