



History The original Government Corners at the four Corners of this Section, also the $\frac{1}{4}$ Section corners on the East and North are in the original positions as set by the Government survey, and are universally accepted as such. But an error was made in the subdivision, placing the center of the section 10.05 ft. too far S. and 98 ft. too far East from this erroneous corner the town of Freewater is laid out as nearly as could be without the use of surveying instruments. The exact lay of the town as nearly as can be ascertained from some of the Original stakes will be shown on page 2.

L.A. Wilson, City Engineer, March 17, 1903.

Note: This is a copy of the plat found at page 1 of the City of Freewater Plat book at Freewater Oregon. The heavy lines and figures are in black ink and the light lines and figures are in pencil. The plat referred to as being at page 2 is a plat of Evans Addition and shows the sectional subdivision lines in relation to the Addition Boundaries.

Hartman & Abstract Company,
Pendleton Oregon,

Sec. 2 50 35
T5N R35 02AC

11-170-13

(5N 35 02)