


Compell - Add - Lamons - Saxton & Pierce July 14<sup>th</sup> 1910

J. S. N. R. 28. 8. W. M.

Chains Links



John U. Kimber County Surveyor  
 assisted by Ernest Niemyer chairman  
 Henry Niemyer "  
 and Arthur Spinning Flagman