

Surveyed for John Buss May 9<sup>th</sup> 1906 J2N 16326

Chain Links

- beginning at Co to Sec 10-11-14 & 15-  
 these points bet Sec 14 & 15-  
 40 02 the 1/4 Sec cor bet Sec 14 & 15-  
 thence North on true line  
 20 01 bet Stone for 1/16 cor  
 40 02 the cor to Sec 10-11-14 & 15-  
 thence west bet Sec 10 & 15-  
 17 95 C.C. to Sec 10 & 15-  
 20 00 bet Jan for 1/16 cor  
 40 05 the 1/4 Sec cor bet Sec 10 & 15-  
 thence South through Center N 1/2 Sec 15-  
 20 01 1/16 corner  
 from the 1/4 Sec cor bet Sec 14 & 15- 1/2 mi  
 North 300 C.C. to Sec 14 & 15-  
 thence N 58° W 478 A 66  
 then N 22° W 2500 Mile Post-  
 " N 22° W 1257 C.C. to Sec 10 & 15-  
 West through Center N 1/2 Sec 15-  
 9 97 Observation Line N 22° W  
 20 00 the Center N 1/2 Sec 15-

John W. Toombs County Surveyor