

Survey for M. D. Scroggs & Parsons.

Chains Links

Tp. - 4 N R 28 E W. M.

Parson acted as chainman.

Beginning at the Sec. Cor. of Sec. 14-15-22-23 of Tp. 4 N R 28 E I run West on Sec.

19 94 Drive a stake for $\frac{1}{16}$ cor. about half way bet. present fence cor. and ditch.29. 91 Drive a stake for $\frac{1}{32}$ cor.39. 88 $\frac{1}{4}$ cor. rock bet. sec. 22-15.I then set inst. over $\frac{1}{16}$ cor. and turn angle of $90^{\circ} 35'$ to left, ~~reverse~~
and run north

5.00 Set stake for cor. of 5 ac. tract.

19. 80 Drove stake for $\frac{1}{16}$ cor. in line fence. - Road here 50 lks. wide - runs E+W.Set up over $\frac{1}{32}$ cor. on S. line and turned angle of $90^{\circ} 05'$ to left and ran North

5 00 set stake for NW. cor. of 5 acre tract.

19. 80 set stake in line with fence ~~with~~ for. corner bet. Parson & Scroggs. - Road 50 lks. wideStarting at the S $\frac{1}{16}$ cor. on Sec. line bet. sec. 14-15 I chain West along road.20 00 $\frac{1}{16}$ cor. stake as set in fence line.

29. 97 cor. as set. bet. Parsons & Scroggs.

39. 94 stake set for Scroggs NW cor. on line fence. Present fence cor. 23 lks. too far West.

March 15-1919

Aubrey E. Perry
County Surveyor.