
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by GLO contract dated May 4th 1887 executed by J.P. Currin and J.E. Noland. Surveyor General field notes state: Set a basalt stone 12x10x10 ins. 8 ins. in the ground marked 1/4 on the N face from which: A pine 12 ins. diam. bears N80°E 24 lks. dist., marked "1/4SBT". A pine 14 ins. diam. bears N45°E 37 lks. dist., marked "1/4SBT".

T1N R35EN-07



Corner brought to county standard by David H. Krumbein in 1979 under Survey M-105-A from original corner evidence. Set a brass cap monument.

Corner accepted by John E. Hollingsworth in Survey Number 88-011-B. Umatilla County monumentation record states: Fd. Brass cap on 2 1/2 ins. G.I.P. 1 ins. above the ground in a rock mound. Fd. 19" fir N2°E., 20.9' with a blaze scar. Fd. 30" pine bearing N86°E., 15.6' with trace of scribes visible in a partially opened blaze. Fd. 10" pine S15°W., 20.7' with corner tag and no blaze scar.

Corner accepted by surveys Partition Plats 1996-25, 1997-38, 1998-40, 2005-34, and 2007-41, and Surveys 08-145-B and 10-131-B.

DESCRIPTION OF CORNER EVIDENCE FOUND:

A 24 ins. diam. Ponderosa pine bears North 84° East a dist. of 15.80 ft., alive and vigorous with healed blaze. A 15 ins. Ponderosa pine bears South 15° West a dist. of 20.50 ft., alive and vigorous with healed blaze.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: From the iron pipe monument:

NEW BEARING TREES:


A 10" Ponderosa Pine bears South 78° East a dist. of 10.75 ft., marked "1/4 S20 BT" A 26" Douglas Fir bears North a dist. of 21.15 ft., marked "1/4 S17 BT"

I hereby certify that the corner was perpetuated on July 16, 2018.

Witness: Kyle A. Tucker, Ryan Skeen



Renewal Date: June 30, 2019



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

18-074-0