

H. C. Cook Aug 9<sup>th</sup> 1910

J 1 S 16 35 S W M

Chains Links

Commencing at NW cor Sec 20 T<sub>1</sub>N  
 South to Sec 19 T<sub>2</sub>N

40 42 the 1/4 sec cor

thence North on True line

20 21 set Post for 1/16 cor thence East through cor NW 1/4 Sec 20  
 20 10 set Post for 1/16 cor in Cent NW 1/4 Sec 20  
 East to Sec 17 T<sub>2</sub>N

40 22 the 1/4 sec corner to Sec 17 T<sub>2</sub>N

thence west on True line

20 11 set Post for 1/16 corner

thence South through Centre NW 1/4 Sec 20

40 40 the 1/16 corner

North on True line

20 20 set Post for 1/16 cor in Cent NW 1/4 Sec 20

John W. Kimbrell