

Field Notes (Continued)

Sta	Bearings	Chains	Remarks	Sta	Bearings	Chains	Remarks
61	S 31° E	26		89	S 82° E	7	
62	S 46° E	4		90	S 11° W	7	
63	S 41° E	10		91	S 44° W	14	
64	S 52° E	16		92	S 46° E	13	
65	S 63° E	9	Barufinas Ranch	93	S 4° E	6	
66	S 28° E	10		94	S 38° W	16	
67	S 7° E	6 17		95	S 8° E	10	
				96	S 65° E	3	
68	S 7° E	5		97	S 13° E	2 22	
69	S 20° W	7					
70	S 19° W	41		98	S 18° E	14	
71	S 23° E	27 18		99	S 30° W	18	
				100	S 31° W	20	
72	S 23° E	13		101	S 16° E	4	
73	South	31	Weatherford Ranch	102	S 49° E	18	
74	S 53° E	2		103	S 26° E	11 23	Colifons Ranch
75	S 4° E	14					
76	S 16° E	10		104	S 20° E	50	
77	S 28° E	8		105	S 55° E	14	
78	S 32° E	2 19		106	S 52° E	16 24	
79	S 32° E	18		107	S 62° E	17	
80	S 31° E	7		108	S 35° E	30	
81	S 6° E	19		109	S 46° E	11	
82	South	13		110	S 35° E	17 25	So intersection of Co Road
83	S 36° E	7					
84	S 46° E	10 20					
85	S 46° E	1					
86	S 68° E	19	Douglas Ranch				
87	S 56° E	17					
88	S 12° E	43 21					

I certify that the within is a correct copy of the field notes of a road surveyed by me from the mouth of Willow creek up said creek to intersect the Co Road from Pilot Rock to Scotts Station

J. H. Sharon  
Co Surveyor.

(Read on page 42)