

Road No 283

Report of Viewers. Field Notes ^{and} Plat of Survey of a change in County Road on the lands of Geo D. Peebler, G. F. Kimery ^{and} W^m Estes on Stage Gulch Road

Report of Viewers

To the Hon. County Court, Umatilla County, Oregon.

We the undersigned viewers in change in County Road prayed for by G. F. Kimery, George D. Peebler ^{and} W^m Estes, ^{and} numbered 283 would respectfully report that we met with the County Surveyor at the time ^{and} place appointed by your Hon. body ^{and} proceeded to view out ^{and} survey said road as prayed for by said petitioners. We find the said surveyed change in road to be some longer than that portion of the old road to be a nullity by the said change is upon so much better ground, that in our opinion travelers would much prefer the change as proposed ^{and} surveyed, the said change in road is now already opened, worked ^{and} traveled for these said reasons we would recommend that the said change be granted.

Viewers { R. J. Murdock
 { Jas J. Johnson

Field Notes of Road Survey No 283.

Met viewers at time ^{and} place appointed ^{and} calling Sam A. Crowell ^{and} Geo D. Peebler to act as chainbearers ^{and} Geo F. Kimery as marker, who were each qualified according to law.

- I commence at crossing of roads at $\frac{1}{4}$ cor between Secs 7 & 8 in T. 3 N. R. 31 E. W. M. set initial post in mound about 2 rods chain S. E. ^{and} run thence north $\text{va. } 22^\circ \text{ E}$
- 40.45 Along traveled road in lane. to initial post in Road No 226, about 30 feet. at Mt P. School House.
- 47.00 Set angle stake against fence, 45 links west of line - Cut A on E. side of fence post. ^{and} turn along road in lane,
- 865° 00' E 80.00 Set 1 mill post against wire fence on N. side of lane
- 54.95 Intersect line running N. & S. through center Sec. 8 T. 3 N. R. 31 E. W. M at Res of Geo D. Peebler, turn thence
- South 64.50 along traveled road to $\frac{1}{4}$ Sec cor bet Secs 8 & 17 in said T. 3.
- 78.50 Intersect old County road - course N. W. set terminus against wire fence, 45 links west of line - The posts are all of size ^{and} marked ^{and} set in mounds as required by law. The road is already opened ^{and} in good condition for travel ^{and} is a much better road than the old, although about 40 chains longer.

Thereby certify the foregoing field notes of the survey of Road change No 283 to be correct.

Jno. C. Arnold, Suror. Umatilla Co. Or.