



Survey not accepted  
 Surveyor refuses to change!

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

W. W. Cramer

OREGON  
 SEPT. 30, 1977  
 WALTER W. CRAMER  
 1423

1030 S.W. 17th  
 Hermiston Ore 97838  
 Tel. 503-567-3471

RECEIVED BY  
 - Umatilla County Surveyor  
 Date: 4/16/2012  
 Rec'd By: J. Oles  
 No.: 12-040-A

Purpose of Survey

To Relocate and set Obliterated original Survey corners of Lot 5, Blk. 2 of Hat Rock Sub. Umatilla Cty. Ore Sect. 15, T5N, R29, EWM. Corners set by retracement of distances and lines of original Plat as shown. Survey by Tape and Transit with 1' of angle Vernier.

NOTES

- ◆ US Corp. of Eng. "Taking Line" Mons. Fnd. (Not shown on Subd. Plat)
- ⊙ Mons. Fnd as Indicated
- Mons. Set " " AL Tags L50-1423
- (xxy) original sub. PLAT
- GP = Gal. Pipe; RB = Conc. Re. Bar; IR = Smooth Iron Rod.

SURVEY FOR BOB HALL  
 Lot 5, Bl. 2 of HAT ROCK Sub.  
 Umatilla Cty. Ore. S15, T5N, R29  
 Scale Solid Lines 1" = 60'  
 " --- " 1" = 60'  
 9-20-89