


**NARRATIVE:**

The purpose of this survey was to establish the east sixteenth corner common to Sections 35 and 2; the North sixteenth corner center to center, and the Northeast sixteenth corner of Section 35.  
 A previous survey by this firm in 1983 subdivided Section 35. Control points set and caps found during that survey were to establish these corners, refer to County Surveyors Draw No. 83-08-B.  
 Bearings are based upon work done by the BLM in 1980.

- denotes set 2 1/2" Brass cap on a 2 1/2" x 30" pipe stamped PLS 933 buried 12" w/ a fence post
- ⊙ denotes set 2 1/2" Aluminum Cap on a 2 1/2" x 30" aluminum pipe stamped PLS 933
- denotes find 1980 BLM 2 1/2" Brass Cap & 2 1/2" x 30" iron pipe
- ⊕ denotes find Umatilla County Surveyor 2" Brass Cap on a 1 1/2" x 30" iron pipe.
- denotes find fence.
- denotes find 5/8" x 30" iron rod with aluminum cap stamped as shown:



<b>KRUMBEIN ENGINEERING LTD.</b> ENGINEERS - SURVEYORS - PLANNERS 381 S.E. Second Pendleton, Oregon	Scale 1"=500'	Drn. By WAP	Draw. No. 04-39C	Revision 1
	Date 10-1-84	Chd. By DHK	Job No. 84-86	Revision 2
Survey for <b>THORNE &amp; PEARSON</b>  Sec 35, T6N, R31E, W1M.		REGISTERED PROFESSIONAL LAND SURVEYOR <i>David H. Krumbein</i> OREGON JULY 17, 1970 DAVID H. KRUMBEIN 933	RECEIVED BY Umatilla County Surveyor Date 10/84 Rec'd By kc No. 84-115-B	