



Stryker-Kimbell Associates  
Pte. 1 Box 316  
Lewis Creek Road  
Summerville, Oregon 97876  
503-534-6905  
12 August, 1989

Office of County Surveyor  
Umatilla County  
Pendleton, Oregon

NARRATIVE per USDA FS Contract 00-04R3-9-1 JEMINA CADASTRAL SURVEY

This survey was performed at the request of the USDA Forest Service, the Umatilla National Forest, headquartered in Pendleton, Oregon.

This survey was performed within Township 4 North, Range 38 East, W.M. as a subdivision of Section 29 to monument and establish the ownership and the boundaries of the public lands within said section, Umatilla County, Oregon.

The basis of bearing was the south line of the southwest one-quarter per record of survey plat K-156-B records of Umatilla County Surveyor.

The survey was performed using a Wild T1 micrometer theodolite and a Wild DI-4L electronic distance meter turned to Wild targets and prisms. A closed random traverse was used to tie all controlling monuments within said section meeting precision standards of one in ten thousand prior to angle balances. A least squares adjustment procedure was used. True line closed loop traverses were performed to establish property lines, and offset methods were used to set steel fence posts along the true property lines. These also met the same precision standards noted above.

There were no lost or obliterated corners--all controlling corners were recovered and section subdivision was based upon their found and tied position. A complete description of all corners found and/or set can be found with the Umatilla County Surveyor's Office in the form of certified and recorded corner recordation forms.

There exists several areas of encroachment found during the posting of the property lines, namely in the form of old fence lines (all down), old cutting lines (both USFS and private), and old blazed lines. The USFS overcut along the north line of the SE1/4, SW1/4; the USFS overcut along the west line of the SW1/4, NW1/4; the private land owner overcut along the north line of the SE1/4, NW1/4; the private land owners down fence encroaches northerly along the north line of the S1/2 of the NW1/4. All these encroachments are old. The private land owner was made aware of these at the time of posting, as he and his wife were on site.

Certified,  
*Edwin A. Stryker*  
Edwin A. Stryker  
Oregon PLS 2060

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*Edwin A. Stryker*  
OREGON  
JULY 15, 1983  
EDWIN A. STRYKER  
2060

RECEIVED BY  
Umatilla County Surveyor  
Date 11-89  
Rec'd by KA