

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 10/08/01**

**CORNER DESIGNATION: 2N32Z11, The North Quarter Corner of Section 4.**

**PREVIOUS RENEWALS/ SURVEYS, ETC.:**

Most recent record is Umatilla County Surveyors Corner Record: 94-109-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found 2 1/2" brass on galvanized iron pipe monument cap 1" above ground level in good condition, marked as shown in monument marking detail.

Per corner record all accessories are intact.

**MONUMENT MARKING DETAIL:**

T2N R32E  
1/4 S33  
S4  
T1N  
1994  
PLS 1106

**LOCATION & COMMENTS:**

Corner falls 16 feet east of Birch Creek.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 710082.96

E = 8632664.50

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801  
  
2N32Z11

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED b1

Umatilla County Surveyors

Date 2-02

By KK

02-47-9