

OREGON CORNER RESTORATION FORM

Section 16 Township 1N Range 32E
County Umatilla Date: August 17, 2009

Corner Designation: 1N32N13

Corner common to sections 15, 16, 21, and 22,
T1N, R32E, W.M., Umatilla County, Oregon.

Previous Renewals / Surveys, etc.

Corner was originally set by Daniel Chaplin under contract No. 107 dated September 21, 1864. His record reads: Set post for corner to sec. 15, 16, 21 and 22 in mound of earth with charred stake, pits &c as per instructions. J. Kimbrell in record of survey in Book 1, Page 422 stated: Set stone. William R. Wells under survey 06-528-C states: No stone found, set aluminum cap and four reference magnets.


x Condition Report Only
Not found
Remonumented
Unrecorded
Surveyed in
Referenced out

Monument and Accessories found: (condition and source)

I found the 2" aluminum cap on a 5/8" iron rebar approximately 10" down in a CRP field.

DIAGRAM

SKETCH



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None. I held the monument by Wells. This certificate is prepared to record the state plane coordinates shown below.

For references:

The monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments
NAD 83/1991 State Plane Coordinate
Oregon North Zone
N = 694,355.97 ift
E = 8,635,561.81 ift

Compass Declination

Surveyors Seal

RECEIVED BY:
Umatilla County Surveyor
Date: 6-10
Rec'd By: SK
No. 10-93-C

Firm / Agency
Witness Tree Surveying
Address
P.O. Box G
Pilot Rock, Or. 97868
Party Chief
Stephen K, Haddock

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Stephen K. Haddock

OREGON
JULY 9, 2001
STEPHEN K. HADDOCK
56295LS

RENEWAL DATE 6-30-11