CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 1 N R 35 E K-10

S	16

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 27" in the ground with a 2 $\frac{1}{2}$ " Aluminum cap marked as shown below, in a collar of stone 1 ft. diam., from which:

NEW BEARING TREES:

A 10" Ponderosa Pine bears South 71° East, a distance of 31.30 feet, marked NW 1/16 S16 BT. A 7" Ponderosa Pine bears South 47° West, a distance of 16.30 feet, marked NW 1/16 S16 BT.

Set a steel fencepost North approx. 1 ft.

I hereby certify that the corner was monumented June 23, 2017. Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.