

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 8/25/95
CORNER DESIGNATION: V-1. Southeast corner Section 25, T1N., R34E., W.M.

V-25

PREVIOUS RENEWALS/SURVEYS, ETC.: Corner originally established by James P. Currin and James Noland under Special Contract dated May 4, 1887.

Surveyor General records state:

Set a basalt stone 9x8x7 ins., 6 ins. in the ground, for cor. to secs. 25, 30, 31 and 36, marked 1 notch on S. and 5 notches on N. edges, from which

- A pine, 40 ins. in diam., bears N. 30°E., 29 lks. dist., marked T 1 N S 30 B T.
- A pine, 15 ins. in diam., bears S.82°E., 285 lks. dist., marked R 35 E S 31 B T.
- A pine, 12 ins. in diam., bears S.48°W., 65 lks. dist., marked S 36 B T.
- A pine, 12 ins. in diam., bears N.88°W., 42 lks. dist., marked R 34 E S 25 B T.

MONUMENT AND ACCESSORIES FOUND: Found a set basalt stone 13" x 8" x 5" under 6" of dirt and roots marked with 5 notches and 1 notch on opposite edges.

A 46" ponderosa pine with 5" overgrowth scribed "S30 BT" on partially healed blaze bears N 35° E, 19.6 feet distance, (record states N 30° E, 29 lks, 19.1 feet).

A rotten stump with pitched over face marked "BT" bears S 35° W, 42.8 feet distance, (record states S 48° W, 65 lks., 42.9 feet). No trace of other bearing trees.

MONUMENT MARKING DETAIL:

T1N
R34E R35E
S25 | S30

S36 | S31
1995
ORLS 1639

MONUMENT SET:

I removed the original corner stone and in its place set: A 1 1/2" diameter by 30" long galvanized iron pipe with a 2 1/2" brass cap, projecting 4" out of the ground with a 2 foot diameter mound of stone, marked as shown in monument marking detail.

An 8" ponderosa pine bears N 40° W, 26.1 feet, marked "T1N R34E S25 BT" on double blaze.

A 7" ponderosa pine bears S 35° E, 36.3 feet, marked "T1N R35E S31 BT" on double blaze.

A 7" ponderosa pine bears S 29° W, 4.8 feet, marked "T1N R35E S36 BT" on double blaze.

Each new bearing tree has a Umatilla County bearing object sign attached above the upper blaze and a brass washer marked PLS 1639 nailed to the face of the lower blaze.

Original bearing trees have a Umatilla County bearing object tag attached alongside the blaze.

LOCATION & COMMENTS:

Corner is in East-West fence line and on the South edge of a jeep road.

COMPASS DECLINATION: 18° East.

Surveyor's Seal

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Witness: William Hanley, PLS 1639
Rodney Lewis, LSPP

William L. Hanley

Umatilla County Surveyor

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Date 10-95

Rec'd By RK

No. 95-169-B

RENEWS 06/30/97