


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 1 N R 35 E W-11



DESCRIPTION OF CORNER EVIDENCE FOUND:

A 28" Douglas Fir with remnants of fence grown over approx. 8" bears South East approx. 7'.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 27" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 19" Douglas Fir bears North 43° East a dist. of 12.70 ft., marked CN 1/16 S33 BT.
A 6" Lodgepole Pine bears North 25° West a dist. of 1.55 ft., marked CN 1/16 S33 BT.


Set steel fence post approx. 1 ft. North

I hereby certify that the corner was monumented on September 10, 2019.

Witness: Kyle A. Tucker



Renewal Date: June 30, 2021



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

19-097-6