

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 9/15/94

CORNER DESIGNATION: A-21. Northeast corner Section 2, T1S., R35E., W.M.

PREVIOUS RENEWALS/SURVEYS, ETC.: Most recent approved GLO Survey was made by James P. Currin and James Noland, under Special Contract dated May 4, 1887. Notes state: "Closing corner to secs. 1 & 2 in T.1S. R.35E., a post 4 ft. long, 4 ins. square, set firmly in the ground, marked with 6 notches on S and 5 notches on W. and 1 notch on E. edges, with S.1 on E. and S.2 on W. faces; other marks are illegible; from which:

- A Fir 14 ins. in diam. bears N45°E. 47 lks. dist.
 - A Pine 12 ins. in diam. bears S35°E. 25 lks. dist.
 - A Pine 10 ins. in diam. bears S15°W. 29 lks. dist.
- Marks illegible."

This corner was originally established by Rufus S. Moore under Contract No. 451, dated June 12, 1882.

MONUMENT AND ACCESSORIES FOUND:

Bearing Trees:

A 20" (m/l) pine stump, bears S 27° W-19.1 feet, uprooted, partly gone, with visible scribing, (Moore bearing tree).

A 22" fir stump, bears N 38° E-29.7 feet, mostly rotten, (Moore bearing tree).

An 18" (m/l) pine stump, bears S 76° E-13.2 feet, stump is broken off, with visible scribing, (Moore bearing tree).

Re-establish corner position at average position by measurement from bearing tree remains.

MONUMENT MARKING DETAIL:

T1N R35E
 CC

 S2 | S1
 T1S R35E
 1994
 PLS 1106

MONUMENT SET:

At re-established corner position, set a 2 1/2" brass cap on a 1 1/4" x 30" galvanized iron pipe, 26" in the ground (marked as shown in monument detail).

New Accessories:

Set steel fence post with witness sign attached 2.4 feet North of monument

A 9" tamarack bears S 49° E-27.3 feet, scribed: T1S R35E S1 CC BT.

A 9" douglas fir bears S 15° E-29.2 feet, scribed: T1S R35E S1 CC BT.

A 12" douglas fir bears S 10° W-47.2 feet, scribed: T1S R35E S2 CC BT.

a 14" ponderosa pine bears S 35° W-64.5 feet, scribed: T1S R35E S2 CC BT.

New bearing trees have a brass washer stamped 'PLS 1106' nailed to the face of the blaze. Attached bearing object and witness signs to all bearing trees, painted a 6" band and face of blaze red.

LOCATION & COMMENTS:

STATE PLANE CO-ORDINATE:

Oregon North Zone, NAD 83/91, U.S. Survey Foot:

N = 680922.48
 E = 8741843.27

RECEIVED BY

Umatilla County Surveyor

Date 2-95

Rec'd by KK

No. 95-16-C

COMPASS DECLINATION: 18° East.

Surveyor's Seal

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801
Party Chief: Robert D. English
Notes: Robert D. English
Witness: F. Scot Munro

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Will R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Renews 4/30/96

RECEIVED BY

Umatilla County Surveyor

Date 2-95

Rec'd By KK

No. 95-16-C