

USDA-FOREST SERVICE

Index
File No. R-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. _____

T 15 R. 35E


R.D. WALLA WALLA County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM

T15 R35E



DESCRIBE CORNER MONUMENT FOUND

NONE - FOUND AN OREGON STATE FORESTRY "K" TAG ON A SMALL FIR. K TAG IS INCRIBED "7' S30°W FB MC 3-13-47 & AWH 6/79"

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FROM THE POINT DESCRIBED AS THE CORNER ON THE K TAG, A 36" FIR BEARS S65°W, 25'±, SCRIBING, "5M", VISIBLE ON A PREVIOUSLY OPENED BLAZE. I BELIEVE THIS POINT TO BE EXTREMELY CLOSE TO THE ORIGINAL CORNER AS TOPOG CALLS N, S, E & W FIT VERY WELL, BUT I DO NOT THINK THE FIR IS AN ORIGINAL B.T.

PHOTO IDENTIFICATION DATA

Photo.No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

THE GROUND AROUND THE CORNER POINT AS IDENTIFIED BY THE "K" TAG HAS BEEN STRIPPED TO MINERAL SOIL BY SOMEONE SEARCHING FOR CORNER POST REMAINS. THE OLDER TREES IN THIS AREA HAVE BEEN BURNT & ARE DOWN & BADLY DECAYED. NO ORIGINAL B.T.I EVIDENCE WAS FOUND.

Signature

Title

Division

Headquarters

Date

7100-52-(3.68)

Dennis L. Gaylord

PLS

1636

6/25/81

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

a post was found at this corner by state highway division in 1954. Coordinates of post: N 659,872.78 E 540,406.05
SEE MAP C-22

12

Index File No. T. R. M. Tract or Surv. No. Cor.

R-21

13