


Index
 File No. B-9
 T LS R. 36E
 Merid. Will.

CORNER RECORD (SEARCH)
 (Ref. FSM 7151.4)

Tract or
 Survey No. _____
 Cor. No. _____

R.D. _____ County UMATILLA
 N.F. UMATILLA State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

2 1/2" GALV. IRON PIPE WITH BLM BR. CAP, MKD. → N 1/6
55 | 54
1984²

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

11" FIR, SCRIBED "N 1/6 55 BT" BEARS 589°W, 29 LKS.
10" FIR, SCRIBED "N 1/6 54 BT" BEARS N 56 1/2°W, 127 1/2 LKS.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____⁷

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

COR. LIES IN SMALL OPEN AREA, ON NE SLOPE,
ABOUT 75 'S. OF A SMALL DRAW, COURSE E.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____⁸

Signature Victor McPhed LS

Division _____

Headquarters _____

Date 4-22-86

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

ATTACHED SIGN 54-4 TO BACK OF BT'S

PAINTED RED BAND AROUND BT'S

SET STEEL POST ABOUT 4 FT. FROM CORNER WITH SIGN 54-9

Work Done By V. MCLIND Title LS Date 6-3-86 State Registration No. 934
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. B-9 T. 15 R. 36E M. WILL. Tract or Surv. No. _____ Cor. _____