

Index
File No. H-3

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. _____

T LS R. 36E R.D. WALLA WALLA County UMATILLA

Merid. WILLAMETTE N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

3 1/4" BLM Brass CAP on 2 1/2" I.P.
RISING 23" ABOVE GROUND

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" FIR, BLAZED & SCRIBED CS 1/16 S 7 BT,
BEARS S 44 1/2° W, 41 LKS, 27.1 FT.
10 1/2" FIR, BLAZED & SCRIBED CS 1/16 S 7 BT,
BEARS N 60 1/2° E, 90 1/2 LKS, 59.7 FT.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

In Shallow Ravine at South-East Corner of
Cleared Area. From Intersection 3032 and 3033
Eastly 1/4 mile, Then Left Fork 3/4 mile to Fence
& SW 1/16, Walk Posted Line to corner

D. Scott
Signature

Title
LS 1844

Division

Headquarters

Date
6-24-85 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NONE

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET STEEL FENCE POST 3 FT. SOUTH OF CORNER.

ATTACHED SIGNS TO POST & BT'S

Painted Red Bands

Work Done By D.E. SCOTT Title SURVEYOR Date 6-24-85 State Registration No. LS 1844
or Agency

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T.15 R.36E W.M. Tract or Surv. No. Cor. CS 1/6 57

H-3