

U. S. Department of Agriculture

FOREST SERVICE

*Umatilla*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *15* R. *36 E* W Mer.

*1/4* Corner common to Sections *20* and *29*

Corner consists of a *rock pile & Stake* (not) in place

State condition *Stake replaced*

Dimensions above ground *213 x 36* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		<i>114 S</i>	
		<i>BT</i>	

Species \_\_\_\_\_ *yp cottonwood*

Diameter \_\_\_\_\_ *10'*

Bearing \_\_\_\_\_ *S40E*

Distance \_\_\_\_\_ *10'*

Do you believe this to be a genuine Land Office Corner *Yes*

If not, why? \_\_\_\_\_

*Vance L. Morrison*  
(Signature)

*11-10-33*  
(Date)

*Proctor*  
(Date)

T. 15 R. 36 E W Mer.

(Make sketch of topography near Corner)

Sec. <u>20</u>	Sec. <u>21</u>
Sec. <u>29</u>	Sec. <u>28</u>

Metal Location Poster is on a Y.P. tree  
tree 9 1/2 inches diameter, on the S  
side of road  
from which this Corner bears S. 31 E  
\_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this  
Corner again.

Use the same rocks at W  
edge of ridge

USDA-FOREST SERVICE

Index

File No. R-7

**CORNER RECORD (SEARCH)**

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.

No. \_\_\_\_\_

T 1S R. 36E

R.D. Pendleton


County Umatilla

Merid. Willamette

N.F. Umatilla

State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No evidence of the orig. corner found during a brief search of the two indicated stub positions. Monument set by RPE 2808 2 1/2" Gal. steel pipe with a 2 1/2" Brass cap properly stamped and firmly set in a mound of stone 4' base, 15" high. Guard post East with "Attention" sign. 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

RPE 2808 10" now 11" Pine S37E-36.2 ft. scribing visible on unhealed double blaze.  
RPE 2808 8" now 8" Pine N83E-46.0 ft. scribing visible on unhealed double blaze. 3

PHOTO IDENTIFICATION DATA

Photo No. 480-207

Filed At. Umatilla N.F.

Object Ident. Two I.P.'s

Ident. By Larry D. Guthrie  
*Signature* 7

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
*Agency* 8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 4

From its junction with Rd. #3102 follow spur 020 approx. 0.6 mile to side draw from East. Go Northwest about one-quarter mile to corner just West of ridge top at base of 12 ft. high rock outcrop.

Larry D. Guthrie  
*Signature*

Title Land Surveyor

Division \_\_\_\_\_

Headquarters \_\_\_\_\_

Date 10/82 7100-52-(3/68) 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By Larry D. Bishop Title Surveyor Date 10/82 State Registration No. 896  
or Agency \_\_\_\_\_  
Certified Cor. Record Prepared? Yes  No  Filed At: \_\_\_\_\_ Date: \_\_\_\_\_

REMARKS

Exchanged signs on guard post to 54-2 and 54-4 replaced "Attention" signs on BT's with sign 54-4 and painted band and blazes red.  
Set guard post South with signs 54-2 and 54-4.

Index File No. T. R. M. Tract or Surv. No. Cor. 12 13

Index  
File No. R-7

**CORNER RECORD (SEARCH)**

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_  
Cor.  
No. R-7


T 1 S R. 36 E

R.D. Pendleton County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is 15 feet below break of ridge on the West side and at the base of a 12 ft. high point of rock outcrop.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_

*Agency*

*James O. Hauler*  
*Signature*

Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_

ORPE 2808

10-21-75

7100-52 (3/68)

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

Set a 2½ " brass cap on a 2" iron pipe 31" long in an earth and stone mound with a 6 ft. steel fence post alongside with sign 54-4 attached.

See sketch of monument markings below:

**ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

A pine, 8" diam. bears N 83° E, 46.0 ft. dist.  
mkd. ¼ S 20 BT.

T 1 S R 36 E  
¼ S 20  
S 29

A pine, 10" diam. bears S 37° E, 36.2 ft. dist.,  
mkd. ¼ S 29 BT.

R P E 2 8 0 8  
1976

BTs have sign 54-3 attached 6" below band of red paint with a brass washer mkd. RPE 2808 nailed flush with BT blaze.

Work Done By. Jas. D. Hanley Title Engr. Date 5-19-76 State Registration No. ORPE 2808  
Or Agency

Certified Cor. Record Prepared ? Yes  No  Filed At: Pendleton Date 8-2-76

**REMARKS**

Attached sign 54-2 to S and E side of 8" pine alongside corner monument.