

USDA-FOREST SERVICE

Index

File No.

T-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No.

Cor.

No.


T 1S R. 36E

R.D. Pendleton County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

N/A

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N/A

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

6

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From its junction with road #3102 follow spur 015-0.4 mile to posted line-corner is 300 ft. North.

3

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

8

Signature Larry D. Bushup

Title Land Surveyor

Division

Headquarters

Date

10/82

7100-52-(3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3" Brass cap in a 5" diameter x 7" concrete cylinder anchored to bedrock by two 5/8" rebar firmly driven.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10" Pipe S78E, 98.6 ft. scribed C/S29BT and
with a 1" Brass disk stamped PLS 896.
14" Pine S5E, 160.7 ft. scribed C/S29BT and
with a 1" Brass disk stamped PLS 896.

Work Done By Larry D. Bishop Title Surveyor Date 10/82 State Registration No. 896
or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

REMARKS

Set guard posts East and South with signs 54-2 and 54-9.
Nailed 54-9 and BT signs to BT's and painted band and blazes red.

Index File No. T. R. M. Tract or Surv. No. Cor. 13