

Index
File No. Z-15

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. Z 15 Cor. No. 1/4 **81**


T 1 S R. 36 E

R.D. Pendleton County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM
T1S R36E



DESCRIBE CORNER MONUMENT FOUND

Brass cap set summer 1972. See reverse side.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found 30" pond. pine, live & good condition, with scribing visible, bearing S54°E 105 ft. dist. from the corner position.
Found uprooted pine, bearing approx. N32°W 78 ft. from the corner position, no scribing visible.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Established corner position N54°W 105 ft. from live 30" pine.



Signature _____ Title _____ Division _____ Headquarters _____ Date _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 30x2½" iron pipe with 3" brass cap marked as shown, 25" in the ground
& raised a mound of stone around the pipe.
From which a new bearing tree:

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A fir 16" diam. bears N3°E, 107.5 ft. dist. marked T1S R36E^{1/4}S34 BT.
Distance taken to a brass washer in the blaze of the new bearing tree.
Set a steel fence post approx. 5 ft. East from corner with Forest Boundary
sign attached.
Used steel tape & magnetic compass with declination equal 20° East.

10

Work Done By D. M. Ferguson Title Land Surveyor Date 7/12/69 State Registration No. 848
or Agency

Certified Cor. Record Prepared ? Yes No Filed At Umatilla Co. Courthouse Date 11/16/72

11

REMARKS

12

Index File No. Z-15 T. R. M. Tract or Surv. No. Cor. 13