

USDA-FOREST SERVICE

Index
File No. N-3

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. No. N-3

T 1S R. 37E
Merid. Willamette

R.D. Pendleton County Umatilla
N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Ran compass course east from found corner. Found 10" tamarack in SE quadrant. Chopped into tree found blaze scribed: $\frac{1}{4}$ S there is a down tamarack approximately 15" diameter in the NE quadrant that could have been other BT.

PHOTO IDENTIFICATION DATA

Photo No.
Filed At.
Object Ident.
Ident. By
Signature.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State Zone
X
Y
Estab. By
Agency

Signature
Bill Moore

Title
Eng. Tech.

Division

Headquarters

Date

7100-52-(3/68)

10/7/77

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed blank F.S. bearing tree and attention posters on the 10" tamarack and blazed line 150' east to bottom of open ridge.

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. _____

13