

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 2N, R 32E., W.M.


Corner Code No. C-9

Note: Monument marked as shown below

History of original corner establishment:

This corner was originally established by D. Chaplin, U.S. Deputy Surveyor, under Contract No. 107, dated August 21, 1884. The original notes state that at the corner a wood post, with charred stake, earth mound and pits, was established for the corner.

In 1900, during County Survey No. 142, John Kimbrell states that he reestablished the corner by proportional measure between the S.E. and N.E. corners of Section 5. Kimbrell's record states that at the corner point set basalt stone 12 by 6 by 6 for 1/4 corner between Secs. 4 & 5. We note that Kimbrell's proportional computation for reestablishment is not correct.



Corner No.
Compass Declination: 18.0

Description of corner evidence found:

None. This corner point falls at a fence corner with fences going south and west. There are a number of loose stones in the area but none could be identified as Kimbrell's corner stone.

Description of monument and accessories established to perpetuate the original location of this corner:

Reestablished the corner by proportional measure between the reestablished N.E. and S.E. corner of Section 5, using the record proportional measure from the original Contract No. 107 record. At the reestablished corner point I set a 2 1/2" brass cap on a 1 1/2" by 30" galv. iron pipe, 28" in the ground and surrounded with a mound of earth and stone.

Referenced the monument as follows. From the new corner monument:

A 1 1/2" plastic cap marked "W.R. Wells PLS 1106", set on a 5/8" by 30" iron rod bears S86°W 14.18'. The reference monument falls in a east-west fence. Set steel fence post near reference monument and attached witness corner and bearing object signs.

A 1 1/2" aluminum cap, marked as shown, set on a 5/8" by 30" iron rod, bears S6°E 18.31'. The reference monument falls in a north-south fence. Set steel fence post near reference monument and attached witness corner and bearing object sign.

Attached witness corner sign to a railroad tie fence corner near the corner monument.

The aluminum cap on the reference monument is marked as follows:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106



Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19....

..... by
(COUNTY OFFICIAL) (DEPUTY)