

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE: 10/08/01**

**CORNER DESIGNATION: 2N32, E-13, The Southeast Corner of Section 4.**

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Most current record is Umatilla County Surveyor's Corner Record No. 88-19-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass disk in a 5" concrete post, 4" above ground level, marked as shown in monument marking detail. The trees used for accessories in the SE and SW quadrants in 1988 have been cut down. There is an old witness sign approximately 1 foot East of Corner. The NW quadrant accessory ("X" in concrete post), still exists.

**MONUMENT MARKING DETAIL:**

UMATILLA COUNTY  
SURVEYOR  
S4 | S3  
S9 | S10  
T2N R32E  
1968

**LOCATION & COMMENTS:**

Corner is located at the Southeast corner of a housing subdivision and the edge of the High School lawn overlooking the new water park.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 736519.08  
E = 8634688.95

**FIRM/AGENCY:** William R. Wells, PLS  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32E13

*Fawn A. Norman*

05  
26  
05

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1976  
WILLIAM R. WELLS  
1106

*renews 6-30-02*

RECEIVED BY

Umatilla County Surveyor  
Date 12-01  
Rec'd By KK  
No. 01-210-9