

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


T 2N , R 32E. , W.M.

Corner Code No. R-1

Note: Monument marked as shown below

History of original corner establishment:

This corner was originally established by Josiah A. Burnett, Deputy Surveyor, under Contract No. 92, dated September 12, 1860. Set a post, drove a charred stake, raised a mound with trench, as per instructions.



Corner No.  
Compass Declination: 18.0°

Description of corner evidence found:

No evidence of corner found. Corner was re-established by single proportion measurement between the West 1/4 corner of Section 19 and the Southwest corner of Section 30, T2N., R32E., W.M..

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 2 1/2" brass cap on 1 1/4" x 30" galv. iron pipe, 10 inches in the ground with a mound of stone and earth to the cap.

Set a steel fence post with a Witness corner sign attached, 4.6 feet North of the monument.

New Bearing Objects:

A 5/8" x 30" iron pin bears N 09° E - 40.9 feet. (Flush with the ground).

"XBO" chiseled in a basalt rock outcropping bears S 49° E - 26.8 feet.

"XBO" chiseled in a basalt rock outcropping bears S 29 1/2° W - 36.8 feet.

A 5/8" x 30" iron pin bears N 57° W - 24.4 feet. (Protruding 4 inches from the ground).

All iron pins are capped with a 1 1/2" yellow plastic cap marked " WR WELLS, PLS 1106". Bearing Object signs are wired to each pin.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*EXPIRES 12/31/94*

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by .....

(COUNTY OFFICIAL)

(DEPUTY)