

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

L - 21
DIAGRAM

History of original corner establishment:

The original corner was established on September 3, 1878, by George S. Pershin under GLO contract No. 293, as follows:

Set stone, 15" x 8" x 5", on north hillside for the 1/4 section corner.

T2S R30E
1/4
S14|S13
PLS 1636
2000

Original corner evidence recovered:

Found the original corner stone solidly set at the north edge of a mound of stones. The corner stone is 13" x 10" x 5", and is plainly marked "1/4" on the east face.

Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 30" flared, galvanized iron pipe 26" into the ground. A 2 1/2 brass cap attached to the pipe is marked as shown in the diagram above. I bury the corner stone to the south of the pipe, and build a mound of stones around the pipe, from which:

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N70°E, 61.2 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S40° 30'E, 104.6 feet.

A 5/8" x 36" iron rod set 36" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S49° 30'W, 117.6 feet.

A 5/8" x 36" iron rod set 36" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N42° 30'W, 99.5 feet.

A 5 foot steel fence post with a "Witness Post" sign attached bears north, 0.8 foot.

I hereby certify the above corner point was perpetuated as hereon described on June 13, 2000.
Magnetic declination set in compass: 18°E.



Renews June 30, 2001

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY
Umatilla County Surveyor
Date 6-2000
Rec'd by KK
No. 00-128-R