

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P - 13  
DIAGRAM

**History of original corner establishment:**

The original corner was established by George S. Pershin on September 6, 1878, under GLO contract No. 293, as follows:

Set a stone, 16" x 7" x 6", for 1/4 section corner.

T2S R30E  
1/4  
S21|S22  
PLS 1636  
2002

**Original corner evidence recovered:**

Found the original corner stone loosely set in a mound of stones. The corner stone is 16" x 6" x 6" and is plainly marked "1/4" on one face.

**Monument and accessories established to perpetuate the original position of this corner:**

In place of the original corner stone, I set a 1" x 18" flared, galvanized iron pipe 5" into the ground to bedrock. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the diagram above. I place the corner stone horizontally alongside the west side of the pipe and build a mound of stones around the corner stone and pipe, from which:

A 5/8" x 24" iron rod set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N50° E, 104.3 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S19° 30' E, 190.5 feet.


A 5/8" x 18" iron rod set 14" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S20° W, 135.5 feet.

A 5/8" x 24" iron rod set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N23° W, 121.9 feet.

I nail a "witness post" sign to a wooden fence post one foot east of the corner.

I hereby certify this corner point was perpetuated as hereon described on July 31, 2002.

Magnetic declination set in compass: 24° E.



Renews June 30, 2003

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY  
Umatilla County Surveyor  
Date 9-02  
Rec'd By KK  
No. 02-216-R