

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

N - 5  
DIAGRAM

History of original corner establishment:

The original corner was established by Daniel Chaplin on November 21, 1864, under GLO contract No. 107, as follows:

Set stone 24" x 8" x 6" for corner to sections 17, 18, 19 and 20.



Corner evidence recovered:

Found the original corner stone loosely set in a mound of stones. The stone is 22" x 10" x 6" and is plainly marked with five notches on the east edge and three notches on the north edge.

Monument and accessories established to perpetuate the original location of this corner.

At the point occupied by the original corner stone, I set a 1" x 30" iron pipe 24" into the ground to bedrock. A 2 1/2" brass cap attached to the pipe is marked as shown in the diagram above. I bury the corner stone along the west side of the pipe and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 S17", attached at ground level bears N47°30'E, 121.1 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 S20", attached at ground level bears S56°E, 101.9 feet.

A 5/8" x 36" iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 S19", attached at ground level bears S43°W, 99.2 feet.

A 5/8" x 24" iron rod set 21" into the ground with a 3/4" brass washer, marked "PLS 1636 S18", attached at ground level bears N58°W, 105.1 feet.

I hereby certify the above corner point was perpetuated as hereon described on April 23, 1998. Magnetic declination: 18°E.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*Dennis L. Gaylord*  
OREGON  
JULY 14, 1978  
DENNIS L. GAYLORD  
1636

Renews June 30, 1999

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on \_\_\_\_\_, 1998.

RECEIVED BY  
Umatilla County Surveyor  
Date 4-98  
Rec'd By KK  
No. 98-65-R