


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-25

History of original corner establishment:

The original surveyor David P. Thompson, 1864, under G.L.O. contract No. 106 set stone 18x12x8 in. for cor. to Secs. 30, 31, 25 & 36

In 1890 under G.L.O. contract No. 551, John C. Arnold subdivided T2S R33E and set closing corner as described "intersecting the W. Bndy. of Tp 500 lks south of cor. to Secs. 25-30-31-36 which is a basalt stone 18x12x6 ins. 8 ins. in ground marked 5 notches on N. corner. I cut 1 notch on S. edge and raised a mound of stone 2 ft. H. by 3 1/2 ft B. over cor."




Description of corner evidence found:

At corner position found 18"x11"x7" stone with 5 notches on north edge & 1 notch on south edge 3" in ground with remains of stone mound partially around stone and partially slid down hill.

Description of monument and accessories established to perpetuate the original location of this corner:

In place of stone set 2 1/2"x30" galvanized pipe with brass cap stamped:



Set pipe 20" in ground with mound of stone to cap and buried original stone alongside.

Bearing Trees:

A Douglas Fir 14" dia. bears N46°W, 24.2 ft, scribed T2S R32E S25 BT.
A Douglas Fir 9" dia. bears S28°E, 58.2 ft, scribed T2S R32E S36 BT.

Attached 54-3 & 54-4 signs to both BT's. Attached brass washer stamped LS1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's red. Attached 54-4 sign to metal post 5' south of corner.

I hereby certify the above corner monument was re-established as herein described on July 31, 1980.

Witnesses: R. Orton
L. Huntsman
D. Allen



Office of.....County Surveyor..... County of.....Umatilla.....
State of.....Oregon..... I hereby certify that the within instrument was filed in this office
for record on the.....day of.....December..... 19.....80
David Brumby by Betty Shatto
(COUNTY OFFICIAL) (DEPUTY)