


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. X-25

History of original corner establishment:

The original surveyor David P. Thompson, 1864, under G.L.O. contract No. 106 set a stone 18x14x6 ins. for 1/4 cor. to section 36.




Description of corner evidence found:

After diligent search, could not find any trace of stone.
(Terr. steep and rocky)

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:



Set pipe 15" in ground with mound of stone to cap.

Bearing Trees:

A Douglas Fir 20" in dia. bears N4°W 47.8 ft, scribed 1/4 S36 BT.
A Ponderosa Pine 20" in dia. bears N51°W 105.3 ft, scribed 1/4 S36 BT.

Attached 54-3 & 54-4 signs to all BT's. Attached brass washer stamped LS1294 to foot blaze of new BT's. Painted blazes and 6" band around all BT's. Attached 54-2 & 54-4 signs to metal post 5' north of corner.

I hereby certify the above corner monument was re-established as herein described on August 20, 1980.

Witnesses: R. Orton
G. Wagoner
G. Lester
J. Anderson



Office of.....County Surveyor..... County of.....Umatilla.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the.....day of.....December.....19.80
David S. Anderson.....by.....B. Skate.....
 (COUNTY OFFICIAL) (DEPUTY)