

USDA-FOREST SERVICE

Index
File No. J-9

T 25 R. 35E

Merid. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


Tract or
Survey No. _____

Cor.
No. _____

R.D. UKIAH County Umatilla

N.F. Umatilla State Ore

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE Appears MISSING Sec Cov.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

26" Fir N15E S9BT - ON ground - scribing showing
18" Fir N61W S8BT - Rotted out
20" Fir S21W S17BT - GONE
40" Pine S21E S16BT - ON ground - scribing showing

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Gentle slope - Two converging
Fence Lines AT corner location.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature

LL Kelly

Title

Division

Headquarters

50

Date

8-83

7100-52-(3-68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.