

OREGON CORNER RESTORATION FORM


Section 24 Township 3N Range 27E
 County Umatilla Date 06-28-02
 Corner Designation: 3N27P21

_____ Condition Report Only
 _____ Not Found
 _____ Remonumented
 _____ Unrecorded
 _____ Surveyed In
 _____ Referenced Out


Previous Renewals / Surveys, etc.
 Oregon Corner Restoration Form by Dennis Edwards dated 6/90.

Goulds 1940 survey set this monument.
 Monument and Accessories Found: (condition and source)
 Found this monument in good condition at the top of a Madison Farm road cut.

DIAGRAM



SKETCH



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET

MAGE GPS tie to TRT Station
 Stanfield East Base
 Latitude 45° 48' 35.52978" N
 Longitude 118° 23' 35.35178" W
 NAD 83 (1994)

Oregon State Plane Coord. - North Zone
 Northing 752924.06
 Easting 8484744.46
 Ortho Height 806.99
 Ellipsoidal Height 737.29

Location and Comments

Compass Declination
20° E

Surveyors Seal

From the intersection of Echo Hwy and Butter Cr.
 Hwy go west on gravel rd 1/4 mile. Then go north
 westerly on gravel road 1/4 miles to corner.

RECEIVED BY:

Firm / Agency

Date: 12-02
 Rec'd By: KK
 No. 02-292-9

Haddock Surveying
 P. O. Box 1574
 Pendleton, OR 97801
 (541) 278-2174

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

David L. Haddock

OREGON
 JULY 12, 1968
 DAVID L. HADDOCK
 852

RENEWS 6-30-03