

**OREGON CORNER RESTORATION FORM**

Section 13,14 Township 3N  
County Umatilla Date: 05/21/10

Range 29E

Corner Designation: 3N29L21

Corner common to sections 13,14 T3NR29E.

Condition Report Only  
 Not Found  
 Remonumented  
 Unrecorded  
 Surveyed In  
 Referenced Out

**Previous Renewals / Surveys, etc.**

Originally Surveyed by Gates. He set a post in a mound of earth in 1859.

**Monuments and Accessories Found: (Condition and Source)**  
None.

**Diagram**



**Sketch**

NAD 83/91  
OREGON STATE PLANE NORTH  
INTERNATIONAL FEET

Wooden Fence Post  
▲●

Wooden Fence posts  
●▲ ●▲

N759105.20  
E8548681.18

Power Pole  
○●

LAT - 45° 44' 26.93726" N  
LON - 119° 08' 32.97602" W

**Monument (s) Set (Procedures and Description)**

A 1 1/2" x 30" Galvanized iron pipe w/ a 2 1/2" Brass capped monument 4" below the surface, stamped as shown above. Set in fenceline.

**References Set:**

- A Pk nail and Brass washer #43406, on a wooden fence post lies S 89° E, 5.45'.
- A Pk nail and Brass washer #43406, on a Power pole lies S 43°30' W, 6.63'.
- A Pk nail and Brass washer #43406, on a wooden fence post lies S 88°40' W, 44.17'.
- A Pk nail and Brass washer #43406, on a wooden fence post lies S 89°20' E, 22.15'.

**Location and Comments**

The corner is 0.5 miles South from the intersection of HWY. 320 and Coppinger Road, and West 0.5 miles.

**Compass Declination**  
17° E

**Surveyors Seal**

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Robert Douglas English*  
OREGON  
JANUARY 11, 2005  
ROBERT DOUGLAS ENGLISH  
43406LS

**RECEIVED BY:**

**Firm / Agency**

Date: 6-10  
Rec'd By: KK  
No. 10-100-R

Survey One, LLC.  
P.O. Box 382  
Pendleton, OR 97801  
(541) 276-2055

RENEWAL DATE: 12/31/11