

OREGON CORNER RESTORATION FORM

Section 14,15,22,23 Township 3N
County Umatilla Date: 04/28/10

Range 29E

Corner Designation: 3N29N17

Corner common to section 14,15,22 and 23 T3NR29E.

_____	Condition Report Only
X_____	Not Found
X_____	Re monumented
_____	Unrecorded
X_____	Surveyed In
X_____	Referenced Out


Previous Renewals / Surveys, etc.

Originally Surveyed by Gates in 1859. He set a post in a mound of earth.


Monuments and Accessories Found: (Condition and Source)

None.

Diagram



Sketch



NAD 83/91
OREGON STATE PLANE NORTH
INTERNATIONAL FEET

N756380.65
E8543427.24

LAT - 45° 44' 00.91134" N
LON - 119° 09' 47.59019" W

Monument (s) Set (Procedures and Description)

A 1 1/2" x 30" galvanized iron pipe with a 2 1/2" brass cap, stamped as shown above. This corner was set at a very old fence corner, which fits dimensionally to the corners West and East of it. This is the apparent best evidence of the corner position, and lines of occupation, that we could find.

References Set:

- A 5/8" x 30" Iron rebar w/rpc #43406 lies S 87°30' W, 45.76'.
- A 5/8" x 30" Iron rebar w/rpc #43406 lies S 0°20' W, 61.33'.
- A 5/8" x 30" Iron rebar w/rpc #43406 lies S 86°45' E, 21.86'.
- A 5/8" x 30" Iron rebar w/rpc #43406 lies East, 55.27'.

Location and Comments

The corner is 1 mile South and 2 miles West of the intersection of Coppinger Lane and Hwy. 320.

Compass Declination
17° E

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. English
OREGON
JANUARY 11, 2005
ROBERT DOUGLAS ENGLISH
43406LS

RENEWAL DATE: 12/31/11

RECEIVED BY:

Date: 1-11
Rec'd By: KK
No. 11-15-R

Firm / Agency

Survey One, LLC.
P.O. Box 382
Pendleton, OR 97801
(541) 276-2055