

**OREGON CORNER RESTORATION FORM**

Section 19,30  
County Umatilla

Township 3N  
Date: 3/8/10

Range 29E

Corner Designation: 3N29R3

1/4 Corner common to Sections 19,30 T3NR29E.

- Condition Report Only
- Not Found
- Remonumented
- Unrecorded
- Surveyed In
- Referenced Out


**Previous Renewals / Surveys, etc.**

Originally Surveyed by Gates in 1859. He set a post in a mound of earth.


**Monuments and Accessories Found: (Condition and Source)**

None. This area appears to have been heavily excavated in the process of leveling for several center pivot irrigation systems in this area. This corner falls in a non-farmed area, but appears to be mowed occasionally.

**Diagram**



**Sketch**



NAD 83/91  
OREGON STATE PLANE NORTH  
INTERNATIONAL FEET

N750630.25  
E8524963.39

LAT - 45° 43' 07.07922" N  
LON - 119° 14' 09.13859" W

**Monument (s) Set (Procedures and Description)**

Set a 1 1/4" x 30" galvanized iron pipe with a 2 1/2" brass cap, buried 21" below surface, stamped as shown above. Set a steel fence post 1' South with Witness Corner sign.

**References Set:** "Deep One" magnets by Berntsen.

- A Silver magnet, 20" deep, lies N 46°40' E, 17.29'.
- A Pink magnet, 21" deep, lies S 17°30' E, 22.87'.
- A Blue magnet, 20" deep, lies S 57°40' W, 20.43'.
- An Orange magnet, 20" deep, lies N 7° W, 20.12'.

**Location and Comments**

From the intersection of Hwy. 320 and Whitehouse Road, go 0.5 miles South, and 0.5 miles East through a farm field.

**Compass Declination**  
17° E

**Surveyors Seal**

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Robert D. English*  
OREGON  
JANUARY 11, 2005  
ROBERT DOUGLAS ENGLISH  
43406LS

**RECEIVED BY:**

Date: 1-11  
Rec'd By: KE  
No. 11-17-R

**Firm / Agency**

Survey One, LLC.  
P.O. Box 382  
Pendleton, OR 97801  
(541) 276-2055

RENEWAL DATE: 12/31/11