

CORNER RESTORATION FORM

Township 3N Range 30E & 31E Section 1,6,12&7 County UMATILLA

State OREGON Date 3-11-2015 Number E-25

Corner Designation : SECTION 1, 6, 12 & 7

- Condition Report Only
- Not Found
- Renewed
- Surveyed In
- Referenced

Previous Renewals ORIGINAL SOURCE OF CORNER


UNDER GLO CONTRACT #81 BY D. THOMPSON DATED
JULY 8, 1859 SET POST

Accessories Found:

NONE

MONUMENT DETAIL

Found Set



BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE:

NORTHING: 767856.845
 EASTING: 8586021.103

Monument & Accessories Set (Procedure and Description)

SET 2 1/2" BRASS CAP ON 1 1/2" PIPE AT GRADE IN FENCE LINE WITH MARKER SIGN ON T-POST, PLACED LAVA ROCK 20"x13"x14" BY MONUMENT.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, N0°39'E 25.08' IN FENCE LINE, BEARING OBJECT SIGN ON T-POST.

SET 5/8" REBAR & CAP PLS 61420 1.5' BELOW GRADE, S87°15'E 5.04'.

SET 5/8" REBAR & CAP PLS 61420 AT GRADE, S1°13'E 26.14' IN FENCE LINE, BEARING OBJECT SIGN ON T-POST.

SET 5/8" REBAR & CAP PLS 61420 1.5' BELOW GRADE, N82°52'W 23.46'.

Sketch of Monument, Accessories and General Area

REGISTERED PROFESSIONAL LAND SURVEYOR

Lance Clark King

OREGON
MAY 10, 2011
LANCE CLARK KING
61420

RENEWS: 6/30/2015

Agency:
CK3, LLC
945 W. ORCHARD
HERMISTON OREGON 97838
OFFICE: 541-567-2345
FAX: 541-567-2305
WEB: CK3LLC.NET
Field Book # 0-289

COUNTY SURVEYOR RECORDING INFO

Received *[Signature]*

Filed 6/12/2015

Survey No. 15-050-G

Drawing No. C-853

Index No. E-25