

OREGON CORNER RELOCATION FORM

Section 11 Township 3N Range 30E
 County Umatilla Date: July 11, 2007

Corner Designation: 3N30G17

Condition Report Only
 Not found
 Remonumented
 Unrecorded
 Surveyed in
 Referenced out


Quarter corner to sections 10 and 11, T3N, R30E, W.M.
 Umatilla County, Oregon.

Previous Renewals / Surveys, etc.


The corner was originally set by William B. Campbell under contract No. 95 dated September 19, 1860. His record reads: Set a post for quarter Section corner, drove a charred stake & raised mound of earth with trench and pits as per instructions.

Monument and Accessories found: (condition and source)

None. The position falls at the intersection of an east - west County road and a field line south.



⊗ = Brass Cap
 • = Rebar Reference



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

I set a 2 1/4" brass cap on a 1 1/2" x 30" galvanized steel pipe at the intersection of the County road centerline and the field line. The cap was stamped as shown in the diagram above. The top of the cap is approximately 6 inches below the surface of the road.

For references I set four 5/8" x 24" iron rebars with 1 1/8" orange plastic caps stamped WTS and 56295LS as described below:

- an iron rebar bears N89°50'48"W, 25.26 feet;
- an iron rebar bears S41°40'43"W, 17.16 feet;
- an iron rebar bears S38°17'47"E, 15.59 feet;
- an iron rebar bears N89°21'06"E, 25.63 feet;

The monument and references were tied using a Trimble R7/R8 RTK GPS

Location and comments

Compass Declination

Surveyors Seal

RECEIVED BY:
Umatilla County Surveyor
 Date: 8-07
 Rec'd By: KK
 No. 07-242-R

Firm / Agency
 Witness Tree Surveying
 Address
 P.O. Box G
 Pilot Rock, Or. 97868
 Party Chief
 Stephen K, Haddock

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Stephen K. Haddock

OREGON
 JULY 9, 2001
 STEPHEN K. HADDOCK
 56295LS

RENEWAL DATE 6-30-09