

OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 4/10/15

CORNER DESIGNATION: The North One-Quarter Corner of Section 9, Township 3 North, Range 31 East, E-11.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner originally established by D.S. Payne, under Contract No. 100, dated 8/1/1861, notes state: Set charred stake with mound trench and pits as per instrs. for 1/4 sec corner.

MONUMENT AND ACCESSORIES FOUND: None.

MONUMENT MARKING DETAIL:

T3N R31E
1 S4
4 S9
2015
PLS 54657

MONUMENT SET:

Re-established corner on parallel of latitude between the Southwest and Southeast corners of Section 4. the field lin visible today is a newer farmed field line that didn't exist in 1956, per viewing of 1956 Farm Service Agency photos. At re-established corner position, set a 2 3/8" brass cap on a 1 1/4" x 30" galvanized iron pipe, 20" below ground level, stamped as shown in "Monument Marking Detail".

From which:

- A silver deep-1 magnet, 20" below ground level, bears North 45° East, 32.7 feet.
- A pink deep-1 magnet, 20" below ground level, bears South 35° East, 40.4 feet.
- An blue deep-1 magnet, 20" below ground level, bears South 46° West, 44.2 feet.
- An orange deep-1 magnet, 20" below ground level, bears North 48° West, 38.0 feet.

Buried bearing object tags with magnets.

LOCATION AND COMMENTS: Corner located in a farmed field.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 767946.12
E = 8599378.95

FIRM: Wells Surveying
P.O. Box 1696
Pendleton, OR 97801

COMPASS DECLINATION: 18° East Surveyor's Seal

Witnesses: Jason Wells, PLS
Dean Roy

/3N31E11



RENEWS: 6-30-16

15-052-C